

Table B. High Maintenance (Turf Grass) Seed Mixtures.

Seed Mixture	Moisture Regime	Sun Light	Salt Tolerance	Seeding Rates (PLS)	
				lbs/ac.	lbs/1000sq ft
Kentucky blue grass use at least 3 varieties	dry-well drained	full-partial	moderate	88-130	2-3
Kentucky blue grass Red fescue	dry-well drained	full	moderate	110 44	2.5 1.0
Tall fescue (turf type)	dry-wet	full-shade	moderate	220-260	5-6
Red fescue Kentucky blue grass	dry-well-drained	full-partial	moderate to high	110 44	2.5 1.0
Kentucky blue grass Perennial ryegrass	dry-well-drained	full-partial	moderate	86 43	2.0 1.0
Red fescue Alkali grass Squirreltail grass	wet - moist	full-partial	high to very high	35 35 15	0.8 0.8 0.35

Seeding Dates

Spring	Northern Illinois	Early spring to June 1
	Central Illinois	Early spring to May 15
	Southern Illinois	Early spring to May 15
Fall	Northern Illinois	August 1 to September 1
	Central Illinois	August 1 to September 10
	Southern Illinois	August 1 to September 20
Dormant	Northern Illinois	November 1 to March 15
	Central Illinois	November 15 to March 1
	Southern Illinois	November 15 to March 1